


## ★ Hysteresis (or) Hysteresis in Ferromagnetic Materials

### ★ Definition:

- ★ When a magnetic material undergoes a complete cycle of magnetization, the variation of magnetic flux density ( $B$ ) with respect to magnetic field intensity ( $H$ ) is represented by a closed curve called a hysteresis loop and the lagging of ' $B$ ' behind ' $H$ ' is referred to as hysteresis.

### ★ Explanation:

- ★ When a specimen of ferromagnetic material is placed in an external magnetic field, it becomes magnetized by induction.



- ★ The magnetization increases rapidly with the applied field until it reaches a certain value, after which it remains constant. This point is known as the saturation point ( $H_{max}$ ).
- ★ When the external field is reduced to zero, the magnetic induction of the material does not return to zero. This remaining magnetic induction is called residual magnetism or retentivity ( $B_r$ ).
- ★ When a sufficient negative field is applied, the residual magnetization becomes zero. The magnitude of this negative magnetic field intensity is called the coercive field or coercivity ( $-H_c$ ).

- ★ If the negative field is further increased, the magnetization in the negative direction increases, reaching a maximum value and then remaining constant. This is called negative saturation or saturation in the opposite direction ( $-H_{\max}$ ).
- ★ As the negative field is decreased back to zero, the negative saturation of magnetization does not follow the initial path. Instead, it creates a new path and reaches a point called negative residual magnetization or negative retentivity ( $-B_r$ ).
- ★ The amount of magnetic field required to bring the residual magnetization back to zero from the negative side is also known as the coercive field ( $H_c$ ).
- ★ Furthermore, with an increase in the positive magnetic field, the magnetization again reaches the saturation point, thus completing a full hysteresis cycle.
- ★ At points where the magnetic field intensity is zero (i.e., at  $B_r$  and  $-B_r$ ), the specimen remains magnetized even in the absence of an external magnetic field. This characteristic allows the material to act as a permanent magnet.
- ★ Therefore, it is observed that the magnetic flux density ( $B$ ) always lags behind the magnetic field intensity ( $H$ ); this lagging of 'B' behind 'H' is what defines hysteresis.
- ★ Hysteresis is an irreversible property, meaning that when the external field is removed, the specimen does not fully return to its original magnetic state.
- ★ Consequently, the energy supplied to the specimen during magnetization is not fully recovered. The remaining energy is lost in the form of heat, and this energy loss is termed "Hysteresis loss."
- ★ This loss is represented by the area enclosed by the hysteresis loop (e.g., abcdefa).

### ★ Classification of Ferromagnetic Materials


- ★ Based on the area of their hysteresis loop, ferromagnetic materials can be classified into two main types:

1. Soft ferromagnetic materials
2. Hard ferromagnetic materials

### ★ 1. Soft Ferromagnetic Materials:

#### ★ Definition:

- ★ These are magnetic materials that can be easily magnetized and demagnetized but cannot be permanently magnetized.



★ **Characteristics:**

- ★ They exhibit low hysteresis loss.
- ★ Their retentivity and coercivity are small.
- ★ They are easily magnetized and demagnetized.
- ★ Their magnetostatic energy is small.
- ★ They possess large values of magnetic susceptibility and permeability.
- ★ They cannot be permanently magnetized.
- ★ They are commonly used to make electromagnets.
- ★ These materials are relatively free from irregularities like strains and impurities.
- ★ Domain wall movement within them is easy.
- ★ They lose their magnetism readily after the removal of the external magnetic field.


★ **Examples:**

- ★ Al-Ni-Co Alloy
- ★ Iron-Silicon Alloys
- ★ Ferrous-Nickel Alloys
- ★ Ferrites (some types)
- ★ Garnets (some types)

★ **Hard Ferromagnetic Materials:**

★ **Definition:**

- ★ These are magnetic materials that are difficult to magnetize and demagnetize but can be permanently magnetized.



★ **Characteristics:**

- ★ They exhibit large hysteresis loss.
- ★ Their retentivity and coercivity are large.
- ★ They are difficult to magnetize and demagnetize.
- ★ Their magnetostatic energy is large.
- ★ They possess small values of magnetic susceptibility and permeability.
- ★ They can be permanently magnetized.
- ★ They are used to make permanent magnets.
- ★ These materials tend to have more irregularities, such as strains or impurities.
- ★ Domain wall movement within them is difficult.
- ★ They retain their magnetism even after the removal of the external magnetic field.

★ **Examples:**

- ★ Iron-Nickel-Aluminum alloys (e.g., Alnico)
- ★ Copper-Nickel-Iron alloys
- ★ Copper-Nickel-Cobalt alloys
- ★ Aluminum-Nickel-Cobalt alloys (Alnico types)
- ★ Cobalt steel
- ★ (Note: While Al-Ni-Co alloys can be hard magnets, specific compositions or applications can make them behave as soft magnets in certain contexts, though this is less common than them being hard magnets. Iron-Silicon is a more typical example of soft magnetic alloys.)